

# SAFETYPOINT



Scrapyard Safety Training

## AIR BAG GAS GENERATOR INCIDENT

A scrap yard worker was cleaning bundles with a torch. The tip of the unit pictured below was sticking out of the bundle. When the worker cut it with the torch, the unit exploded and hit the man in the groin.

- Be sure you know what you're cutting before you put a torch to it.
- Inspect your scrap to make sure none of these end up in your bales.



“Toyota Deutschland”



Discharged



Not discharged



Institute of  
Scrap Recycling  
Industries, Inc.

Voice of the Recycling Industry

Send comments or questions to: [isrisafety@isri.org](mailto:isrisafety@isri.org)