

FALL PROTECTION FOR CONVEYORS

Here's an alternative fall protection system on conveyors borrowed from one of the world's largest shippers. Weld steel supports to the sides of conveyors. Then run steel cable through these supports. These cables also provide tie-off points for a body harness and lanyard.

WARNING: ALWAYS LOCKOUT THE CONVEYOR BEFORE WALKING ON IT, EVEN WITH THIS OR ANY OTHER FALL PROTECTION SYSTEM.



This e-mail was produced by the Institute of Scrap Recycling Industries, Inc. For more information, visit us on the Web at www.ISRI.org. For comments or suggestions about *For Your Safety*, e-mail joebateman@isri.org

October 19, 2010