

Are your torchmen going through lots of boots?
Here's an idea to make them last a little longer:



Removable steel toe caps can be worn outside regular steel toed boots and help save the leather boots from the rigors of hot slag dropping and burning while torching.

Produced by the Institute of Scrap Recycling Industries

www.isri.org

www.isrisafety.org

Comments/questions?

isrisafety@isri.org

October 11, 2011