

# SAFETYPOINT



Scrapyard Safety Training

## INSPECT YOUR SLINGS

The entire web sling must be **inspected regularly** and it shall be **removed from service** if ANY of the following are detected:

- Sling identification tag is missing or not readable.
- Holes, tears, cuts, snags or embedded materials.
- Broken or worn stitches in the load bearing splices.
- Knots in any part of the sling webbing.
- Acid or alkali burns.
- Melting, charring or weld spatter on any part of the web sling.
- Excessive abrasive wear or crushed webbing.
- Signs of Ultraviolet (UV) light degradation.
- Distortion, excessive pitting, corrosion or other damage to fitting(s).
- If provided, exposed red core yarn. However if damage is present and red yarns are not exposed DO NOT USE the sling.
- Any conditions which cause doubt as to the strength of the web sling.

OSHA Guidance on Safe Sling Use:

[www.osha.gov/dsg/guidance/slings/synth-web.html](http://www.osha.gov/dsg/guidance/slings/synth-web.html)



Voice of the Recycling Industry

Institute of  
Scrap Recycling  
Industries, Inc.

Send comments or questions to: [isrisafety@isri.org](mailto:isrisafety@isri.org)

# PUNTO DE SEGURIDAD

Capacitación en seguridad para depósitos de chatarra

## INSPECCIONE SUS ESLINGAS

La eslinga entera debe **inspeccionarse regularmente** y será **eliminada del servicio** si se detecta CUALQUIERA de los siguientes elementos:

- Falta la etiqueta de identificación o no es legible.
- Orificios, desgarros, cortaduras, enganchones o materiales incrustados.
- Costura rota o gastada en empalmes que soportan cargas.
- Nudos en alguna parte de la eslinga.
- Quemaduras por ácido o álcali.
- Derretimiento, carbonización o salpicones de soldadura en cualquier parte de la eslinga.
- Desgaste abrasivo en exceso o tejido destrozado.
- Señales de degradación por luz ultravioleta (UV).
- Distorsión, hoyos excesivos, corrosión u otros daños al (a los) accesorio(s).
- Si se ha suministrado, el estambre de núcleo rojo expuesto. No obstante, si los daños están presentes y el estambre rojo no está expuesto NO UTILICE la eslinga.
- Cualquier situación que generaría dudas sobre la fuerza de la eslinga.

Orientación de la OSHA sobre el uso seguro de la eslinga:

[www.osha.gov/dsg/guidance/slings/synth-web.html](http://www.osha.gov/dsg/guidance/slings/synth-web.html)



Voice of the Recycling Industry

Institute of  
Scrap Recycling  
Industries, Inc.

Envíe sus comentarios o preguntas a: [isrisafety@isri.org](mailto:isrisafety@isri.org)



## Training Session Sign-In Sheet

Topic \_\_\_\_\_

Instructor \_\_\_\_\_

Location \_\_\_\_\_

Date \_\_\_\_\_

PRINT NAME	SIGNATURE
1.	
2.	
3.	
4.	
5.	
6.	
7.	
8.	
9.	
10.	
11.	
12.	
13.	
14.	
15.	
16.	
17.	
18.	
19.	
20.	