

How Important Is Your Personal Protective Equipment (PPE)?

An ISRI member who melts aluminum sent in these photos after an incident where molten metal splattered back onto a worker. The employee that was wearing the PPE in the photos below was happy he had it on. He only received minor burns. Imagine is he wasn't wearing it or wearing it properly.



This e-mail was produced by the Institute of Scrap Recycling Industries, Inc. For more information, visit us on the Web at www.ISRI.org
For comments or suggestions about For Your Safety, e-mail barneyboynton@isri.org

